



Brand:	Seat	Mileage(km):	180958
Model:	Arona	Number of doors:	5
Model type:	1.0 TSI Style Business Intense Plus Org.NL	Vehicle length (cm):	
License plate:	K708LJ	Vehicle width (cm):	
Report code:	5355	Vehicle height (cm):	
Chassis number:	VSSZZKJZMR065355	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	20/01/2021	Power(kw):	70
First NL req.:	20/01/2021	Transmission	Manual
Color:	Grey <input checked="" type="checkbox"/> Metallic	Number of gears	5
Weight (kg)(kg):	1164	Displacement(cc):	999
Empty weight(kg):	1064	Number of cylinders:	3
Wheelbase (cm)(cm):	257	Fuel type:	Petrol
Top speed (km/h):	182	Fuel tank capacity:	
Cons. in the city (l/100 km):	5.6	EU category:	Euro 6
Cons. outside the city (l/100 km):	4.2	Energy label:	B
Average consumption (l/100 km):	4.7	NL Tax Rate %:	
Acceleration (s):	11.5	CO2 (g/km):	107
Cargo space (l):	1164	Nb. of Axles:	2
Perm. max weight (kg):	1660	APK date:	20/01/2027

opties

<input checked="" type="checkbox"/> Alloy wheels	<input checked="" type="checkbox"/> Exterior mirrors in car body color	<input checked="" type="checkbox"/> Climate control
<input checked="" type="checkbox"/> Digital dashboard	<input checked="" type="checkbox"/> Privacy glass	<input checked="" type="checkbox"/> Climate control (analog)
<input checked="" type="checkbox"/> Daytime running lights	<input checked="" type="checkbox"/> Rain sensor	<input checked="" type="checkbox"/> Climate control (digital)
<input checked="" type="checkbox"/> Licht Sensor	<input checked="" type="checkbox"/> Rear wiper	<input checked="" type="checkbox"/> Climate control (L/R separated)
<input checked="" type="checkbox"/> bots waarschuwing systeem	<input checked="" type="checkbox"/> Rear view camera	<input checked="" type="checkbox"/> Large screen navigation
<input checked="" type="checkbox"/> Anti-lock braking system	<input checked="" type="checkbox"/> Rear parking sensors	<input checked="" type="checkbox"/> Keyless entry
<input checked="" type="checkbox"/> ABS	<input checked="" type="checkbox"/> Front parking sensors	<input checked="" type="checkbox"/> Keyless entry/start/stop
<input checked="" type="checkbox"/> Airbag(s)	<input checked="" type="checkbox"/> Rear-seat folding (equal parts)	<input checked="" type="checkbox"/> Keyless start/stop
<input checked="" type="checkbox"/> Audio	<input checked="" type="checkbox"/> Rear-seat folding (unequal parts)	<input checked="" type="checkbox"/> Electrically operated rear windows
<input checked="" type="checkbox"/> bots herkenning systeem	<input checked="" type="checkbox"/> Baggage separation net	<input checked="" type="checkbox"/> Electrically operated front windows
<input checked="" type="checkbox"/> Central locking system	<input checked="" type="checkbox"/> Luggage cover	<input checked="" type="checkbox"/> Electrically folding mirrors
<input checked="" type="checkbox"/> Fog lamps	<input checked="" type="checkbox"/> USB connection	<input checked="" type="checkbox"/> Electrically adjustable mirrors
<input checked="" type="checkbox"/> Start/stop system	<input checked="" type="checkbox"/> Bluetooth streaming	<input checked="" type="checkbox"/> Electrically heated driver's seat
<input checked="" type="checkbox"/> Power steering	<input checked="" type="checkbox"/> DAB+	<input checked="" type="checkbox"/> Electrically heated passenger seat
<input checked="" type="checkbox"/> Front seats adjustable in height	<input checked="" type="checkbox"/> Radio/CD player	<input checked="" type="checkbox"/> Central armrest front
<input checked="" type="checkbox"/> Multifunctional steering wheel	<input checked="" type="checkbox"/> Bluetooth car kit	<input checked="" type="checkbox"/> Audio control on the steering wheel
<input checked="" type="checkbox"/> Remote central locking	<input checked="" type="checkbox"/> Radio	<input checked="" type="checkbox"/> Leather steering wheel
<input checked="" type="checkbox"/> Roof rail (black)	<input checked="" type="checkbox"/> WiFi	<input checked="" type="checkbox"/> Pedestrian safety system
<input checked="" type="checkbox"/> Metallic finish	<input checked="" type="checkbox"/> Cruise control (adaptive)	<input checked="" type="checkbox"/> Dead angle assistance
<input checked="" type="checkbox"/> LED headlights	<input checked="" type="checkbox"/> Cruise control	
<input checked="" type="checkbox"/> LED rear lights	<input checked="" type="checkbox"/> Airconditioning	

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather	Alloy	205/60 R16	Vredestein	4
Tire left rear	All weather	Alloy	205/60 R16	Vredestein	7
Tire right front	All weather	Alloy	205/60 R16	Vredestein	4
Tire right rear	All weather	Alloy	205/60 R16	Vredestein	7

Additional information

No. of keys:	2 <input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet: (serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Half stof/leder		<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	13/07/2023
No. of headrests:	5	Last turn mileage(km):	119130
			<input checked="" type="checkbox"/> Vehicle special usage (None)

⚠ Cleaning

- ☒ Clean inside (Interior is clean)
- ☒ Clean outside (Cleaning)

🔧 Damages

⊕ Not acceptable



Bonnet - Dent




Front bumper - Scratch



Tailgate/ lid - Dent



Rear bumper - Scratch



Rear right door - Restyle dent



Bestuurderstoel beschadigd

🔧 Damages

⊕ Acceptable

⚙ Extra options



