

Inspected by: Rob Datema



Brand:	BMW	Mileage(km):	191289	
Model:	X5	Number of doors:	5	
Model type:	xDrive40i High Executive Org.NL M-pakket	Vehicle length (cm):		
	Pano Bowers&Wilkins Luchtvering	Vehicle width (cm):		
License plate:	XP302Z	Vehicle height (cm):		
Report code:	7585	Vehicle body type:		
Chassis number:	WBACR610X0LH97585	Traction:	Front+Rear	
Type of vehicle:	Luxury	Power(kw):	250	
First int. reg.:	26/02/2019	Transmission	Automatic	
First NL reg.:	26/02/2019	Number of gears	8	
Color:	Black Metallic	Displacement(cc):	2998	
Weight (kg)(kg):	2135	Number of cylinders:	6	
Empty weight(kg):	2035	Fuel type:	Petrol	
Wheelbase (cm)(cm):	298	Fuel tank capacity:		
Top speed (km/h):	243	EU category:	Euro 6	
Cons. in the city (I/100 km):	10.6	Energy label:	D	
Cons. outside the city (I/100 km):	7.5	NL Tax Rate %:		
Avarage consumption (I/100 km):	8.7	CO2 (q/km):	197	
Acceleration (s):	5.5	Nb. of Axles:	2	
Cargo space (I):	2135	APK date:	08/03/2027	
Perm. max weight (kg):	2800			

¢c opties

~	Alloy wheels
$\overline{\mathbf{v}}$	Leather upholstery
~	Air suspension
~	Digital dashboard
~	4x4 performance
~	Daytime running lights
~	Licht Sensor
~	Towing hook
~	bots waarschuwing systeem
~	Anti-lock braking system
~	ABS
~	Airbag(s)
~	Audio
~	bots herkenning systeem
~	Central locking system
~	Fog lamps
~	Start/stop system
~	Power steering
~	Front seats adjustable in heig
~	Multifunctional steering whee
~	Remote central locking
~	Sports package (exterior)
~	Roof rail (black)
\checkmark	Metallic finish
~	Panoramic roof (electrical)
~	Laser headlights
	Laser headlights (adaptive)
~	LED rear lights
~	Exterior mirrors in car body c

Exterior mirrors in car body color

~	Exterior mirrors with step light
	Privacy glass
$\overline{\mathbf{v}}$	Rain sensor
\sim	Rear wiper
\sim	360 ° camera system
$\overline{\mathbf{v}}$	Rear view camera
$\overline{\mathbf{v}}$	Rear parking sensors
$\overline{\mathbf{v}}$	Front parking sensors
$\overline{\mathbf{v}}$	Towbar with retractable ball
$\overline{\mathbf{v}}$	Rear-seat folding (equal parts)
$\overline{\mathbf{v}}$	Rear-seat folding (unequal parts)
~	Luggage cover
$\overline{}$	Trunk opens electrically
$\overline{}$	USB connection
$\overline{\mathbf{v}}$	Bluetooth streaming
$\overline{}$	DAB+
~	Bluetooth car kit
$\overline{\mathbf{v}}$	Radio
$\overline{}$	WiFi
$\overline{}$	Cruise control (adaptive)
~	Cruise control
~	Head-up Display
~	Sports package (interior)
~	Black top interior
~	Airconditioning
	Airconditioning in the back
~	Climate control
~	Climate control (analog)
~	Climate control (digital)

~	Climate control (L/R separated)
~	Large screen navigation
\checkmark	Keyless entry
\checkmark	Keyless entry/start/stop
~	Keyless start/stop
~	Electrically operated rear windows
~	Electrically operated front windows
~	Electrically folding mirrors
~	Electrically adjustable mirrors
~	Electrically adjustable driver's seat
~	Electrically adjustable driver's seat (including memory)
~	Electrically adjustable passenger seat
~	Electrically adjustable passenger seat (including memory)
~	Electrically heated driver's seat
~	Electrically heated passenger seat
~	Central armrest front
~	Extendable passenger seat
~	Extendable driver's seat
~	Adjustable lumbar support driver's seat
$\overline{\mathbf{v}}$	Adjustable lumbar support passenger seat
~	Audio control on the steering wheel
~	Electrically adjustable steering wheel
~	Leather sports steering wheel
~	Leather steering wheel
~	Switch flippers
~	Heated steering wheel
$oldsymbol{a}$	Lane assistance
~	Pedestrian safety system
~	Dead angle assistance

O.	Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	275/35 R22	Continental	7
Tire left rear	Summer	Alloy	315/30 R22	Continental	7
Tire right front	Summer	Alloy	275/35 R22	Continental	7
Tire right rear	Summer	Alloy	315/30 R22	Continental	7

No. of keys:	2 Luxury key	Instruction booklet		Airco works
Interior color:	Brown	Maintenance booklet:	(door universeel)	Odorless
Upholstery:	Leder			Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	17/02/2025	✓ Display ok
No. of headrests:	5	Last turn mileage(km):	178305	✓ Vehicle special usage (None)

A Cleaning

- Clean inside (Interior is clean)
- Clean outside (Polishing)

Damages

Not acceptable








Rear bumper - Scratch



Rear bumper - Scratch



Windscreen - Pip



Deurpaneel RV automatische vergrendeling ontzet

Damages

Acceptable

¢^a Extra options





























