



| | | | |
|---|---|-----------------------------|------------|
| Brand: | Peugeot | Mileage(km): | 147503 |
| Model: | 3008 | Number of doors: | 5 |
| Model type: | 1.6 e-THP Aut. Allure | Vehicle length (cm): | |
| License plate: | SZ811K | Vehicle width (cm): | |
| Report code: | 4038 | Vehicle height (cm): | |
| Chassis number: | VF3M45GZWJS084038 | Vehicle body type: | |
| Type of vehicle: | Luxury | Traction: | Front |
| First int. reg.: | 29/06/2018 | Power(kw): | 121 |
| First NL reg.: | 29/06/2018 | Transmission | Automatic |
| Color: | Black <input checked="" type="checkbox"/> Metallic | Number of gears | 6 |
| Weight (kg)(kg): | 1375 | Displacement(cc): | 1598 |
| Empty weight(kg): | 1275 | Number of cylinders: | 4 |
| Wheelbase (cm)(cm): | 268 | Fuel type: | Petrol |
| Top speed (km/h): | 206 | Fuel tank capacity: | |
| Cons. in the city (l/100 km): | 7.3 | EU category: | Euro 6 |
| Cons. outside the city (l/100 km): | 4.8 | Energy label: | C |
| Average consumption (l/100 km): | 5.8 | NL Tax Rate %: | |
| Acceleration (s): | 8.9 | CO2 (g/km): | 129 |
| Cargo space (l): | 1375 | Nb. of Axles: | 2 |
| Perm. max weight (kg): | 1950 | APK date: | 28/03/2027 |

opties

| | | |
|--|--|--|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Halogen headlights | <input checked="" type="checkbox"/> Cruise control |
| <input checked="" type="checkbox"/> Digital dashboard | <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> Airconditioning |
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Airconditioning in the back |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> Exterior mirrors with step light | <input checked="" type="checkbox"/> Climate control |
| <input checked="" type="checkbox"/> Towing hook | <input checked="" type="checkbox"/> Privacy glass | <input checked="" type="checkbox"/> Climate control (analog) |
| <input checked="" type="checkbox"/> Anti-lock braking system | <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Climate control (digital) |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Climate control (L/R separated) |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Front parking sensors | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Towbar with detachable ball | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> Rear-seat folding (equal parts) | <input checked="" type="checkbox"/> Electrically folding mirrors |
| <input checked="" type="checkbox"/> Start/stop system | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts) | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Adjustable lumbar support driver's seat |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> Bluetooth streaming | <input checked="" type="checkbox"/> Adjustable lumbar support passenger seat |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> DAB+ | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Roof rail (silver) | <input checked="" type="checkbox"/> Bluetooth car kit | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> Radio | <input checked="" type="checkbox"/> Switch flippers |
| <input checked="" type="checkbox"/> Panoramic roof (electrical) | <input checked="" type="checkbox"/> WiFi | <input checked="" type="checkbox"/> Lane assistance |

Tires

| Tire position: | Tire type: | Wheel type: | Tire size: | Tire brand: | Tire profile depth (mm): |
|------------------|------------|-------------|------------|-------------|--------------------------|
| Tire left front | Winter | Alloy | 225/55 R18 | Michelin | 4 |
| Tire left rear | Winter | Alloy | 225/55 R18 | Michelin | 6 |
| Tire right front | Winter | Alloy | 225/55 R18 | Michelin | 4 |
| Tire right rear | Winter | Alloy | 225/55 R18 | Michelin | 6 |

Additional information

| | | | | |
|--------------------------|-----------------|-------------------------------------|--|--|
| No. of keys: | 2 | <input type="checkbox"/> Luxury key | <input type="checkbox"/> Instruction booklet | <input checked="" type="checkbox"/> Airco works |
| Interior color: | Black | Maintenance booklet: | (serviceboekje (papier)) | <input checked="" type="checkbox"/> Odorless |
| Upholstery: | Half stof/leder | | | <input checked="" type="checkbox"/> Clean inside (Interior is clean) |
| No. of seats: | 5 | Stamp date: | 28/03/2023 | <input checked="" type="checkbox"/> Display ok |
| No. of headrests: | 5 | Last turn mileage(km): | 118780 | <input checked="" type="checkbox"/> Vehicle special usage (None) |

Cleaning

☒ Clean inside (Interior is clean)

☒ Clean outside (Cleaning)

Damages

⊕ Not acceptable



Front bumper - Scratch



Front bumper - Ontzet



Front bumper - Break




Front left door - Dent



Front left door - Dent



Rear left screen - Restyle dent



Rear right screen - Restyle dent



Front left door - Restyle dent



Windscreen - Pip




Damages

⊕ Acceptable

Extra options









AUTOF▲CTOR
SOFTWARE FOR AUTOMOTIVE