



Brand:	Opel	Mileage(km):	192177
Model:	Astra Sports Tourer	Number of doors:	5
Model type:	1.4 Aut. Turbo Sport   Org.NL	Vehicle length (cm):	
License plate:	99XNT3	Vehicle width (cm):	
Report code:	9111	Vehicle height (cm):	
Chassis number:	W0LPD8EC6C8099111	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	29/06/2012	Power(kw):	103
First NL req.:	29/06/2012	Transmission	Automatic
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears	6
Weight (kg)(kg):	1503	Displacement(cc):	1364
Empty weight(kg):	1403	Number of cylinders:	4
Wheelbase (cm)(cm):	269	Fuel type:	Petrol
Top speed (km/h):	198	Fuel tank capacity:	
Cons. in the city (l/100 km):	9.1	EU category:	Euro 5
Cons. outside the city (l/100 km):	5.4	Energy label:	B
Average consumption (l/100 km):	6.8	NL Tax Rate %:	
Acceleration (s):	10.8	CO2 (g/km):	159
Cargo space (l):	1503	Nb. of Axles:	2
Perm. max weight (kg):	2045	APK date:	29/06/2025

## opties

- ☒ Alloy wheels
- ☒ Daytime running lights
- ☒ Licht Sensor
- ☒ Towing hook
- ☒ Anti-lock braking system
- ☒ ABS
- ☒ Airbag(s)
- ☒ Audio
- ☒ Central locking system
- ☒ Fog lamps
- ☒ Start/stop system
- ☒ Power steering
- ☒ Front seats adjustable in height
- ☒ Multifunctional steering wheel
- ☒ Remote central locking
- ☒ Roof rail (black)
- ☒ Metallic finish
- ☒ Halogen headlights
- ☒ Exterior mirrors in car body color
- ☒ Rain sensor
- ☒ Rear wiper
- ☒ Rear parking sensors
- ☒ Towbar with fixed ball
- ☒ Rear-seat folding (equal parts)
- ☒ Rear-seat folding (unequal parts)
- ☒ Luggage cover
- ☒ Bluetooth streaming
- ☒ CD changer
- ☒ Radio/CD player
- ☒ Radio/CD/MP3 player
- ☒ Bluetooth car kit
- ☒ Radio
- ☒ Cruise control
- ☒ Airconditioning
- ☒ Climate control
- ☒ Climate control (analog)
- ☒ Climate control (digital)
- ☒ Climate control (L/R separated)
- ☒ Large screen navigation
- ☒ Electrically operated front windows
- ☒ Electrically adjustable mirrors
- ☒ Audio control on the steering wheel
- ☒ Leather steering wheel

## Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather	Alloy	215/50 R17	Hifly	6
Tire left rear	All weather	Alloy	215/50 R17	Vredestein	7
Tire right front	All weather	Alloy	215/50 R17	Hifly	6
Tire right rear	All weather	Alloy	215/50 R17	Vredestein	7

## Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Half stof/leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	28/05/2024	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	186234	<input checked="" type="checkbox"/> Vehicle special usage (None)

## Cleaning

- ☒ Clean inside (Interior is clean)

☒ Clean outside (Cleaning)

## Damages

⊕ Not acceptable



Front left screen - Dent



Front bumper - Break




Bonnet - Paint repair



Front left door - Paint repair




Rear left door - Paint repair



Rear left screen - Dent



Rear bumper - Scratch



Left C- column - Bird droppings



Rear right door - Dent



Aircopump Defect - Storing Airbag Door Defecte Gordel



Bestuurderstoel beschadigd+Versnellingspook beschadigd



Bestuurderstoel beschadigd+Versnellingspook beschadigd

## Damages

⊕ Acceptable





